

**4600 Series**

# **candy<sub>2</sub>O** TM **TRUE CANDY PERFORMANCE**



**4650**  
**Blood Red**



**4651**  
**Sunset Magenta**



**4652**  
**Tequila Yellow**



**4653**  
**Lemon Yellow**



**4654**  
**Grabber Orange**



**4655**  
**Marine Blue**



**4656**  
**Midnight Blue**



**4657**  
**Caribe Blue**



**4658**  
**Ultra Violet**



**4659**  
**Deep Purple**



**4660**  
**Poison Green**



**4661**  
**Emerald Green**



**4662**  
**Dirt Track Brown**



**4663**  
**Red Oxide**



**4664**  
**Black**

Mix with 4030 Mix Additive | Balancing Clear 30% per volume or more. 4030 is a flow-enhancing, urethane resin additive which improves film formation & durability.

Optional – Lower viscosity by reducing with 4012 High Performance Reducer / 4020 Automotive Reducer.

Apply 4 - 6 semi-wet coats to achieve color. Flash Time: 10 min. between coats, 60 min. before clear in ideal conditions. Allow for extended drying times & reduce with 4020 Reducer in cold or humid conditions.

Apply 4040 Non-Reactive Barrier over **candy<sub>2</sub>O** color to prevent bleed-through.

**AUTO-AIR**  
**COLORS** TM